

# Release Notes TwinCAT Tria-Link Library

---

## 3.9.4: (SVN1326) bugfix 0

fix: prevent invalid fast publish axis data during trialink startup (first time boot)  
fix: Omit reset of foreign subscriptions at trialink boot

## 3.9.3: (SVN1314) bugfix 0

fix: If the AboSubscriber received no abos, there was no interpolation: Caused a wrong actual position update  
new: actual velocity output variable added (act\_vel) for TL\_Axis2 and TL\_AxisSlow  
chg: set act\_vel and act\_err to zero if simulation is on

## 3.9.2: (SVN1312) bugfix 3

chg: The smooth interpolator is now selected by default  
fix: Direct feed issues in DMA situations  
chg: Minimum firmware release for the TL/1 is now 1.10.63  
fix: rebooting Trialink without prior Trialink.Execute:=FALSE could cause RegisterWrite address problems  
chg: The error 070 now also reports if Trialink.callFast is not faster than callSlow (fix1)  
fix: Clear the message string if the messageId changes  
fix: check acceleration feed forward only if OfflineFeedForward is active. (fix2)  
fix: Support TL\_Trialink for legacy axes: (MC\_axis.intern.messageLegacy was not set True within TL\_AxisSlow) (fix2)  
chg: With new interpolater setpoint filter can be switched off (fix3)  
new: Separate the messages descriptions for TwinCAT Trialink from TwinCAT EtherCAT (fix3)  
fix: Register offset for Ffx, Ffv, Ffa corrected (fix3)  
fix: Condition for float40 register read fixed (fix3)

## 3.9.1: (SVN1232) bugfix 0

new: Smooth interpolator TL\_Axis2::intern.interpolator1.mode =Interpol5\_SMOOTH\_XXXXXXX

## 3.9.0: (SVN1228) bugfix 3

new: First official release for the TL/Rev1 PCIe board including DMA, see SCN010 for braking changes  
new: TL\_Trialink2 now sends XVA triplets by default, see Trialink.pll.enforceXVATriplets  
new: error 79 for an adapter without driver  
chg: Trialink.Config.FastFilterFrequency is now also the corner frequency for XVA-based interpolation using TL\_Trialink2  
new: Twincat events default settings do not throw events anymore  
chg: TL\_Axis2::messageId for axis messages instead of from errorId  
chg: The TAM System Explorer can detach a TwinCAT Axis similar to EtherCAT

### 3.8.2: (SVN1201) bugfix 5

new: Support Trialink.Config.DmaDisable parameter instead of Trialink.Trialink.Pci.DmaEnable  
fix: Initialize fifos to account for dma restart, turn off tx DMAs for TL/1 FW 0x8CB  
fix: DirectFeed: Current calculation for offline feed forward (fix2)  
fix: Fixed division by gear\_factor of the feed forward current and one sample shift corrected (fix3)  
new: TL\_Trialink2 now sends XVA triplets by default, see Trialink.pll.enforceXVATriplets (fix4)  
fix: TL\_Axis2 objects in simulated mode must not try to access errorCounters (fix5)

### 3.8.1: (SVN1178) bugfix 17

chg: Improve the axisPathInterpolator and use mode Interpol4\_MAV\_XXXXXX as default setting (fixes 3 and 5)  
new: Axis State Disabling  
chg: MaximumStoppingTimeBeforeBrake and BrakeTimeBeforeDisable are not deprecated anymore but default set to zero  
fix: actual position interpolators were not always updated (fix 4)  
fix: polynomial coefficients are transmitted based on a scale of 100 us, not as XVA (fix 9)  
fix: MaximumBrakingTime = 0 must not skip stop for legacy drives (fix 10)  
new: In simulation mode of TL\_Trialink act\_pos = commanded position (fix 10)  
fix: Allow ResetError in enabled state (fix 12)  
fix: In simulation mode, we should not propagate errors (fix 13, without SVN 1170)  
fix: Revert axisPathInterpolator default mode back to Interpol4\_XXXXXX (fix 14)  
fix: Wrong interpolation timebase for TL\_Trialink (fix14) and wrong rounding in tbl.ResamplingSteps (fix 15)  
fix: Streaming mode interpolator (fix 17)

## 3.8.0: (SVN1127) bugfix 18

new: Support TL0400 adapters in adapter mode TL\_Trialink2 with DMA and fast publish for act\_pos, act\_err and digitalInputBits  
new: TL\_Axis2::digitalInputBits: Use Enum DigitalInputBits as a mask  
chg: (!) Obsolete MaximumStoppingTimeBeforeBrakeDepreciated and BrakeTimeBeforeDisableDepreciated  
chg: Default Homing-Type is DriveControlled  
chg: Remove loopback action during boot  
new: Minimum FW Release Adapter 1041 -> 1302 (because of bug in adapter FW 1301)  
chg: reduce TL\_CH\_AX\_MAX from 32 to 16  
new: Trialink.linkErrorCounter shows sum of all drive CRC counters  
TL\_Axis2::TL\_MC\_AXIS\_REF.linkErrorCounters.errorCountLink1/2 shows error details  
fix: publishMaster2Slave must wait for valid register from axis boot before starting  
fix: publishMaster2Slave must be disabled with last generation drives (fix 14)  
fix: Prevent calling publishSlave2Master callFast until the slow task finished (fix 14)  
fix: The actual position must be calculated with the dedicated function in the fast task (fix 14)  
chg: CNC: Sercos Interface Stub, which is required, if an axis is removed and added again (fix 14)  
chg: CNC: MAIN\_FAST to GEO Task (fix 14)  
chg: CNC: Station Address starts with 10 (fix 14)  
fix: wrong data type for actual position in DMA mode for new gen drives (fix 16)  
fix: No tracking in simulation mode (fix 16)  
fix: Remove DMA for Timestamp. Leave DMA for rest (fix 17)  
fix: Gear factor was not used for actual position in DMA mode (fix 18)

## 3.7.5: (SVN1096)

new: Direct feed is now also supported with stream mode (TL\_DirectFeedResampling2 has to be used)  
chg: With TSD firmware >= 4.3 position latch is executed on drive for digital inputs with sampling rate of 10kHz  
chg: Digital inputs renamed from AuxIn1..6 to DigIn1...Dig6 to be consistent with hardware manual  
fix: Direct feed: Check is now done just for direct feed axes (bugfix1)  
fix: Position latch: version check corrected (bugfix 2)  
fix: Direct feed: df-stream does now also support simulated axes (bugfix 2)  
fix: Position latch: version check corrected (bugfix 3)  
fix: Avoid int32 over-run in timestamp wrap situations with Trialink.Config.FastBufferTicks\*FAST-Cycle > 2.5 ms (bugfix 4)  
chg: Wait one tick after diagnostic stop before stop logging  
new: New axis errors up to 316 AxisCommandError  
fix: Include TL\_AboSubscriberMaster5 again (bugfix 6)  
fix: Extended TL\_GetCommutationPosition for register2 (bugfix 7)

fix: TL\_MC\_RegisterRead type mask was not evaluated correctly (bugfix 7)  
fix: Switch off command removed as this could interrupt the enabling sequence (bugfix 8)  
fix: RL\_MC\_Brake and TL\_BrakeConfigGet updated for TSD80 (bugfix 9)  
fix: Switch off axes in case of old drives to avoid STO error - see also bugfix 8 (bugfix 10)  
fix: The check for second master in the ring should only be done once to prevent misleading error 069 (bugfix 11)  
fix: Error 317 is set in case PLC is trapped in disabling state (bugfix 12).  
new: DPRAM addresses (\* 1300 \*) (\* 1304 \*) (bugfix 12).  
chg: Default ResetAdapterOnBoot is now FALSE, was TRUE but disabled completely in Function block (bugfix 12).  
fix: init of MC\_MoveSynchronized::Asettings was not done on restart (bugfix 12).  
fix: Withdraw of error 317 and return to run mode in this case. Log signals added. (bugfix 13)  
fix: If STO started in Disabled state, it sometimes showed STO-Error instead of STO-Warning due to a drive state transition issue  
fix: Add debug code to MoveAbsolute (bugfix 15)

### 3.7.4: (SVN1008)

new: Broadcast globaltime every 5 seconds (bugfix 3)  
chg: MoveSynchronized2 issues a stop if execute is set to FALSE  
This way we can stop streaming without a drive StreamLossError  
chg: Actual position is commanded position in simulation mode  
chg: use method ActualPositionFast(Trialink:=Trialink) to get interpolated positions in the fast task

### 3.7.3: (SVN996)

new: Report file generation "triamec-report-2018.txt" on start of TaskExceedCompensation  
chg: default Trialink.Config.FastBufferTicks := 7  
fix: reference move caused stream loss error as data stream stopped before coupling was released (bugfix 1)

### 3.7.2: (SVN982) requires FW>2083 for TSD-drives

new: Signals.Homing.State and Distance, old Homing state  
Signals.General.HomingState removed  
chg: removed Config.Encoder, use drive config  
Parameters.PositionController.MasterPositionSource instead (FW>2082)  
chg: For TSD-drives we show the actual velocity instead of the commanded velocity in the state telegram

chg: Changes to allow homing with option module implemented.  
new: Fast stop implemented  
fix: RDEeDRVERR\_PowerLinesNotOk is interpreted as warning if  
RDSeDRVST\_NotReadyToSwitchOn

### 3.7.1: (SVN913)

new: Optimized bus access if using TL\_Trialink2 and TL\_Axis2 instead of  
TL\_Trialink, TL\_AxisSlow, TL\_AxisFast (FW>=5050 (TS) 2097 (TSD))  
Trialink.Config.FastFilterFrequency is the corner frequency of the commanded  
position filter  
new: Additional input Trialink.Diagnostics.aux allows logging external input data  
fix: replace constants enabled (bugfix 8)

### 3.7.0: (SVN891)

**!! breaking:** This library requires FW>2087 on TSD devices due to the extended homing state feature

new: TL\_RegisterRead allows accessing 4 registers at once but has no Reg12\_40 and  
Reg4\_DWORD outputs anymore  
fix: TL\_PositionLatchReg2 can now latch DigInputs, but with bad timing accuracy  
(SLOW\_TASK)  
new: TL\_MC\_HOME supports drive controlled homing for TSD drives (FW>2087)  
chg: The register layout was modified to account for new positionlatch features  
new: Extended state in cyclic abo used for homing state

### 3.6.0: (SVN865+)

chg: Optimization of FIFO tail access saves system load!  
new: register entries for identification, positionUnit, masterPosition, analogOut  
chg: breaking register changes:  
    OptionModule.FirmwareId renamed to FirmwareRel  
    TOU1[0] renamed to AnalogIn  
chg: Modifications to avoid warnings with compiler newer equal 3.1.40.20  
chg: DirectFeed: Interface modified.  
chg: DirectFeed: Test added to check if velocity and acceleration are within the  
limits.  
chg: DirectFeed: Events for error publication added.  
chg: DirectFeed: Check if table position at the end of the table matches the  
commanded cnc position.  
fix: DirectFeed: Modulo calculation for position check fixed.

### 3.5.0: (SVN799+)

new: Function blocks for direct feed re-sampling added  
chg: Modifications used for direct feed re-sampling added

### 3.4.1: (SVN782+)

new: Reference on adjacent EncoderIndex for TSxxx drives (special application)  
use ConfigurationManager settings:  
ReferenceMethod := TL\_Config.ReferenceMethod.Marker  
ReferenceFirstMask := 512; // instead of TL\_Config.ReferenceFirstInput.ExtIoA

### 3.4.0: (SVN774)

new: Support 24V digitalInput for homing of TSD-drives (same as for old drives)  
(latching not in drive, but in Twincat)  
chg: new entry Config.Encoder replaces TL\_MC\_Power.EncoderIndexForActPosition  
chg: Support for FW2077, which does no longer support old register style  
chg: BrakeTimeBeforeDisable is discarded with newer drives (TSD)  
because brake time parameter is a config register parameter with newer drives

### 3.3.0: (SVN745)

chg: remove debug signal TL\_MC\_AXIS::rx\_test and corresponding  
TL\_MC\_Power::pub\_aux  
chg: no set position zero during boot. These changes do only apply for TSD-Series  
drives  
chg: Register uses URI-offsets now and is not compatible for TSD80 FW < 2071  
URI take more than 20 bits: extend internal register offset range to 22 bits  
chg: rename General.Parameters.DriveName to General.Parameters.DeviceName  
new: support for absolute endat with TSD80 EncoderPersistency, ReferenceDone,  
Digital Encoder Signals  
new: RCTtCommutationCommands2, Encoder Velocity

### 3.2.1: (SVN730)(TC2 SVN678)

chg: homing is now also supported for TSD80  
chg: general enhancement of TSD80 support  
fix: if axes are coupled, homig did not work in some cases

### 3.2.0: (SVN713)(TC2 SVN678)

new: support for new current controller features of FW2071 of TSD80  
chg: Changes of the drive register layout! Incompatible to earlier FW of the TSD80!

### 3.1.0 (SVN704, Lib310.0, TC3 only)

new: allow receiving five (single) values per abo  
new: TSD80 support: add register layout 19 MC\_AXIS.register2 and support for doubles

### 3.0.5: (SVN692, Lib 305.4)

new: ReferenceType Tama, see AN108  
fix: Check for Session handler garbage collector limit, fixed  
chg: PLL correction time was 2.5\*fastTaskTime, now it is constant 25ms.  
chg: Diagnostic files show position error instead of actual position:Err is not interpolated, act can be seen from cmd in tracking situation(BugFix 4)  
chg: Diagnostics: adaptations for Explorer scope  
chg: reorganize error and event priorities  
chg: avoid double read of publisher abos  
fix: wrong type of PositionController.ControlOutputCurrentQ  
new: Object TL\_AboSubscriberMaster5 receives 5 single float values  
Object TL\_AboSubscriberMaster receives 1 Float40 and 3 single float values (old)  
new: add missing commit option for Axis Environment  
chg: message 075 not trialink "down", but short "shutting down"  
chg: disable of moving axis first tries an emergency stop  
ifMaximumStoppingTimeBeforeBrake<>0  
chg: pll: adjust with sample time, different windows for boot and error179  
chg: remove obsolete events: 131, 136, 138, 139, 141, 144  
new: couple warning/error: sync 178/179 on pll sync problems  
new: task exceeds compensation

### 3.0 (SVN639, Lib302.0)

chg: Compatibility changes for TwinCat3... The following are breaking changes:  
variable "method" in homing parameter not allowed in TC3 -> ReferenceMethod  
all axis parameters are now set in TL\_AxisSlow.Config  
move Trialink.FastHandler.pll.BufferTicks to Trialink.Config.FastBufferTicks  
move TL\_AxisSlow.MC\_axis\_Home.Position to TL\_AxisSlow.referencePosition  
chg: Error 069 has now a smaller priority than 070. New events 178/179  
new: Diagnostic logfile generated on axis errors  
set path in Trialink.Config.RootFolder

an empty path or Trialink.Config.DiagnosticMode is used to disable the feature

the number of files in this folder is limited to Trialink.Config.DiagnosticNumberOfFiles

chg: move library\_version to Diagnostics

new: Add errors for STO firmware 1040, no parallel errors 130+260, changed event file

new: Trialink.Config.TcEventShowReferenceInfos FALSE disables homingmove information messages

new: Trialink.Config.TcEventShowWarnings FALSE disables all warningmessages

new: 4th order interpolator for commanded positions accounts for highdynamic trajectories

new: TL\_publishSlave2Master for ts<>ts\_Fast or ts/0.1ms<>n

new: TL\_MC\_MoveAbsolute can now react in MAIN\_FAST, see AN108

chg: sample codes: new TL\_CNC and TL\_CNC\_AX with task exceed compensation capability

## 2.2 (SVN553, Lib226)

new: Preparation FOR DMA with rx-iso, rx-asy, AND tx-sdram

new: Disable axis errors if Trialink down. STO errors may be configured in Trialink.Config

new: High resolution actual position

new: More registers for tama and position control parameters

chg: TL\_AboSubscriberMaster flexible interpolation and modulocapability on src1

chg: MoveAbsolute and MoveVelocity now signal 152=CommandAborted if anaxis error stops the move before reaching the final state (standstill or ContinuousMotion)

new: Trialink events "Booting" and "Timeout"

chg: tiob: remove unused tRefTick, replace TL\_TiobFast byTL\_AboSubscriberMaster;

chg: publish: new fifo and SingleInterpolator for TL\_AboSubscriberMaster

new: each axis has its own event source for simultaneous display

new: Homing: add search info and show them in the event-display

## 2.1 (SVN502, Lib219)

chg: bug fix Float40 of lib

chg: rename FPGA localbus device DEVencoder\_in\_out to DEVencoder\_DigIn

chg: faster pll initialization

new: Position-latch feature for digital IOs

chg: recover MC\_Power on communication down (\*)

chg: default direction of moveAbsolute is now shortestway (importantfor modulo axes)

new: timeout error if boot not successful for 20 seconds

chg: improve detection of two masters in the loop

new: readyToOperate output of axis module (bridge voltage and STOdetection)



new: distinguish errors and warning for STO and bridge voltage  
fix: message events block fixed new error problem  
new: independent TwinCat errors for axis and (power/homing)  
chg: prios of errorId of TL\_AxisSlow  
    (1. axis error or warning 2. homing error 3. power error)  
fix: dualport ram sync problem on rx\_iso fifo and sync warning  
fix: TL\_publishSlave2Master bug  
chg: always set axis position to zero on ring boot

## 2.0 (SVN476, Lib216)

new : major release with changes listed in AN160 (TL\_Trialink,  
TL\_publishSlave2Slave, Homing)  
new : Support STO  
new : AN122 for CNC-Error 70091 in Manual und Auto Mode  
fix : 12 hour bug  
chg : turn off pwm if MC\_Power.enable=FALSE

## 1.8 (SVN 393, LIB 177)

fix : Endat 2.1 for more than 32 bits  
change: nci-sample code with same structure as cnc

## 1.7 (SVN 383, LIB 176)

fix : moveSync does "shortest move" for proper init of Modulo axes  
fix : Homing Setposition bug.  
new : SetPosition zero during communication startup  
new : generalized register access  
change: new homing sequence statemachine  
change: rename EnableManager to AxisGroup1 and make global  
change: Triamec is now global  
change: HMI based on Visual Expres 2010  
new : smart sync to avoid PLL not locked errors  
change: Endat 2.1: Improve error reporting and retry

## 1.6 (SVN279, LIB 1.6.7)

support new AxisErrors, Endat, modulo spindle, improve interpolator  
direct sync in fasthandler, no sync task required anymore  
cleanup CNC parameters  
change: replace cnc FB "TL\_AxisPath" by lib FB "TL\_AxisFast"

but without IN/OUT components. This allows using a coordinate trafo  
change: replace cnc FB "TL\_AxisModule" by lib "TL\_AxisSlow"  
change: ReferenceEnable instead of ReferenceStart  
This allows controlled resetting of all axes homing flags  
note: encoder was removed because auto-calib is default > FW1030  
to use fast encoder or Endat 2.1 see Application Notes.

## 1.4 (SVN 204)

changed homing behaviour: Clear Homing by Execute:=FALSE  
support stopping by an external event (e.g., endswitch-tama)  
support brake feature

## 1.3 Changes to the Beckhoff Sample Code of the HMI:

simplify T-access, see HLI\_DoChannelTFunction  
moved CNCSystem.T\_cmd to CNCSystem.Channel[nChan].T\_cmd  
moved PLC\_PRG/HLI\_SetAxisTrackingOperation and HLI\_SetAxisFeedHold to  
TL\_CNC\_Status

We removed the following commands in the PLC\_PRG

- HLI\_SetAxisTrackingOperation in PLC\_PRG
- HLI\_SetAxisFeedHold

because these are already written in TL\_CNC\_FromPlc

also be aware, that

- PLCAxisEnable is the global variable of the GUI for enable.