

Firmware Build_FW1055_FF1565 (22.11.2018)

DspFirmware: Build 1055
Release Date: \$Date: 2018-11-12 10:17:15 +0100 (Mo, 12 Nov 2018) \$\br/>**SVN Revision:** \$Revision: 28741 \$\br/>**RLID:** 4&5&6 & 16
Remarks: supporting TSx5x RevB,RevC&RevD and TSP350&700 Rev0,Rev1 Drives,

New features:

-

Bug Fixes:

-

Changes:

-

FpgaFirmware: Build 1565

Release Date: 2018-11-22

New features:

-

Refactoring:

- Send permanently errors when ethernet gap duration is saturated. this helps to recognize an open ring.

Bug Fixes:

- Debouncing PLL phase error in order to NOT react to the first phase error who could be caused by an failure of the ethernet (bit error rate)